

LASER **TACHOMETER**

PLT-5000

Measuring Range

6.0 - 99.999 RPM

The PLT-5000 Pocket Laser Tachometer accurately measures RPM and Surface Speed using contact or non-contact measurement techniques. This batterypowered unit is extremely compact for convenient portable use and is supplied in a rugged and attractive plastic housing that is ergonomically designed for optimum comfort.

When measuring RPM in the non-contact measuring mode, the PLT-5000 emits a precision laser beam that is aimed at a small piece of reflective tape, which is affixed to the rotating target.

The PLT-5000 is extremely easy to operate and quickly converts from non-contact operation to contact operation by screwing the contact adapter in place. In addition to RPM's, a wide variety of engineering units for surface speed and length are user-selected via the front panel buttons. Units include; feet per minute, meters/min, yards per minute, inches per minute and more.

A built-in memory stores up to 10 measurements plus minimum, maximum, average and last.

FEATURES

- FREE NIST-traceable calibration certificate
- Sharp Visible Laser Beam
- Up to 60" Range
- Measures RPM and surface speed and length
- 14 memories
- Displays in Metric or English Readings
- One year warranty
- Simple One Button Operation



PLT-5000 Complete Kit



PLT-5000

Data & Specifications

Data & Specifications

Display 5 digit 0.47" (12mm) height LCD

RPM Measuring Range Contact: 6.0-20,000 RPM (limited for safety reasons)

Non-Contact: 6.0-99,000 RPM

Surface speed 6" Wheel (m/min) 1.0-3,810, (yards/min) 1.0-4,166.4 (inch/min) 36-99,999

(feet/min) 3.0-12,499

Length (Using 6" wheel) (M) 0.2-99,999-(yards) 0.2-99,999 -(feet) 0.5-99,999

Total RPM 1-99,999

Accuracy Revolution 6.0-599.9 rpm± 1rpm, 600-99,999 rpm:± 0.006% & ± 0.5 digit

Surface speed, length 0.4% and ± 1 digit

Memory function 14 Reading are stored in memory and retained for five minutes (Last, Max, Min,

average, and 10 selectable measurements.)

Update timeOne SecondDetectionLaser DiodeAuto Power Off5 MinutesBatteries Included3 AA 1,5V

Low Battery IndicatorFlashing "LO BAT" in displayOver Range IndicatorFlashing "OVR" displayOperating Temperature32-111°F (0-45 °C)

Case Construction ABS Resin

Dimensions 4.55" L x 2.52" W x1.24"H (115.5 mm x 64 mm x 3.15 mm)

Length with contact adaptor: 149 mm

Weight 6 ounces (160 g)

Accessories Storage Case, Cone Adapter, Funnel Adapter, Master Wheel (6"), Contact

adapter, 3 AA batteries, 25 reflective tapes, NIST Certificate, Instructions